

FDA Home³ Medical Devices⁴ Databases⁵

Class 2 Device Recall SPECTRUM Pump



[510\(k\)⁷](#) | [DeNovo⁸](#) | [Registration & Listing⁹](#) | [Adverse Events¹⁰](#) | [Recalls¹¹](#) | [PMA¹²](#) | [Classification¹³](#) | [Standards¹⁴](#)
[CFR Title 21¹⁵](#) | [Radiation-Emitting Products¹⁶](#) | [X-Ray Assembler¹⁷](#) | [Medsun Reports¹⁸](#) | [CLIA¹⁹](#) | [TPLC²⁰](#) | [Inspections²¹](#)

New Search

[Back to Search Results](#)

**Class 2 Recall
SPECTRUM Pump**



Date Posted	October 01, 2014
Recall Status¹	Open
Recall Number	Z-2738-2014
Recall Event ID	69122²³
Premarket Notification 510(K) Number	K042121²⁴
Product Classification	Pump, Infusion²⁵ - Product Code FRN²⁶
Product	SPECTRUM Pump, Model No. 35700BAX. Intended to be used for the controlled administration of intravenous fluids.
Code Information	Software Versions 5.02.06, 6.02.06, and 6.02.11; Affected Serial Numbers: 712090, 723687, 723842, 724966, 725820, 735977, 751130, 752124, 755174, 768538, 771990, 774743, 781406, 783736, 784698, 794466, 805797, 808901, 809113, 812462, 815932, 842120, 857926, 858672, 862085, 863721, 865630, 873459, 889597, 890260, 903748, 912619, 920574, 920589, 956346, 957394, 965402, 966684, 976931, 977550, 978361, 983979, 984066, 984129, 984475, 985946, 987538, 993445, 995291, 996014, 996389, 1013037, 1004377, 1014565, 1014962, 967887, 950671, and 938428.
Recalling Firm/Manufacturer	Baxter Healthcare Corp. 25212 W. Illinois Route 120 Round Lake, Illinois 60073-9799
Manufacturer Reason for Recall	One Service Technician may not have correctly serviced specific Sigma Spectrum Infusion Pumps according to established procedures during the time period of 5/5/2014 through 6/3/2014.
FDA Determined Cause²	OTHER/UNDETERMINED: Under Investigation by the firm
Action	Initial notification was initiated via telephone call by the Baxter Medina Service Center on 8/28/14 to all affected Sigma SPECTRUM Infusion Pump consignees. URGENT DEVICE CORRECTION Letters (dated 9/03/2014) were sent to the consignees via USPS first class mail on 9/03/14 formally informing them of the recall. The letters identified the affected product, the description of the issue, the hazard involved, as well as, the actions to be taken by customer. Customers are being instructed to immediately remove the pump from use and return the pump to Baxter for inspection. The firm will provide replacements. Customers are to contact Baxter Healthcare Medina at 800-356-3454 for technical questions regarding the letter.
Quantity in Commerce	USA: 56 units, Canada: 2 units
Distribution	Worldwide Distribution -- USA and Canada.
Total Product Life Cycle	TPLC Device Report²⁷

¹ For details about termination of a recall see [Code of Federal Regulations \(CFR\) Title 21 §7.55²⁸](#)

² Per FDA policy, recall cause determinations are subject to modification up to the point of termination of the recall.