

July 06, 2016

To: Distributors, Sales Representatives, and Operation Managers

Subject: URGENT FIELD SAFETY NOTICE - REMOVAL

FSN/FSCA: FA 2016-08

Affected Product:

Avenir® Müller Stem 6 Lateral uncemented- REF: 01.06010.106, LOT: 4023094

Avenir® Müller Stem 4 Standard uncemented- REF: 01.06010.004, LOT: 4022860

Dear Sirs,

Zimmer GmbH is initiating a voluntary removal of two lots Avenir Müller Stems (combination material number/ lot number is indicated above) that may be in your inventories. The Avenir Müller Stem 6 lateral uncemented might be placed in the packaging of the Avenir Müller Stem 4 standard uncemented and vice versa.

Our records indicate that you may have received one or more of the affected products.

Risks

- 1) A slight delay in the surgery time might occur if after the discovery of the issue prior implantation, a new product has been made available to finalize the surgery accordingly.
- 2) If no similar implant is available, the doctor might choose a one size bigger stem and further raps the bone for preparation which induces a delay in surgery. Potentially the length of the new implant size might create the dissymmetry in patient's leg.
- 3) The surgeon might have to change the surgical approach and chose a different product conducting to a delay during the surgery or even interrupt / postpone the surgery if there is no appropriate available solution.
- 4) The surgeon might use a standard stem instead of a lateral stem. For the standard stem the offset is 6mm smaller and therefore an increased laxity of the hip might result. This could conduct to a risk of luxation, pain or revision surgery.

Your Responsibilities

- 1. Review the notification and ensure affected personnel are aware of the contents.
- 2. Locate all affected product identified above and quarantine them immediately.
- 3. Carry out a physical count of all affected product in your territory and complete the Inventory Return Certification Form (Attachment 1). Email a completed copy of Attachment 1 to fieldaction.emea@zimmerbiomet.com
- 4. Return any affected product within your possession and from hospital accounts within your territory. Clearly mark the outside of all return packages, "Recall," and include a copy of the Inventory Return Certification form (Attachment 1) with your return shipment(s).



- 5. Provide an additional accounts form to fieldaction.emea@zimmerbiomet.com for any hospitals to which you provided affected product that Zimmer Biomet has not already notified.
- 6. If after reviewing this notification you have further questions or concerns please contact your local Zimmer Biomet representative.

Vigilance/ Reporting Information

This voluntary notification will be reported to the local Competent Authorities.

Any adverse reactions experienced with the use of these products, and/or quality problems may also be reported according to MEDDEV 2.12-1 Rev. 8 or any relevant requirements to the local health authority in your country.

Please keep Zimmer GmbH informed of any adverse events associated with this device or any other Zimmer Biomet product. Adverse events may be reported to Zimmer Biomet at winterthur.per@zimmerbiomet.com, or to your local Zimmer Biomet representative.

Kind regards,	



Attachment 1 Certificate of Acknowledgement

IMMEDIATE RESPONSE REQUIRED -TIME SENSITIVE ACTION NEEDED

Inventory Return Certification Form FSN/FSCA: FA 2016-08

Affected	Pro	du	ct.
Allecteu	110	uu	UL.

Avenir® Müller Stem 6 Lateral uncemented- REF: 01.06010.106, LOT: 4023094 Avenir® Müller Stem 4 Standard uncemented- REF: 01.06010.004, LOT: 4022860

Account	Name:				
Account	Address:		Phone Number:		
	eturn the affected products lot number, and quantity:	s to the following address	with a spreadsh	eet containin	g item
		Zimmer Biome International Logistic Attn: Tim Now Max-Immelmann-A 79427 Eschbach G	s GmbH ak llee 12		
	Credit My Account: _	OR Send	a Replacement:		
	arch for the affected lots has	s been performed and all av	ailable affected	Check one	
		s been performed and all av	ailable affected	Check one	e of the fol
	arch for the affected lots has greturned to Zimmer Biome Item No.	s been performed and all avet. If No, please specify:	ailable affected Qty to be.	Check one	
ts are bein	arch for the affected lots has greturned to Zimmer Biome Item No.	s been performed and all avenue. If No, please specify: Lot No. ificate of Acknowled	ailable affected Qty to be.	Check one Yes Returned	No
By signing notice.	arch for the affected lots has ag returned to Zimmer Biome Item No. Certi	be been performed and all average. If No, please specify: Lot No. If if icate of Acknowled the required actions have be	Qty to be. Signature	Check one Yes Returned ordance with the	No

Please do not return recalled product with other returns.

FA 2016-08



July 06, 2016

To: Hospitals and Surgeons

Subject: URGENT FIELD SAFETY NOTICE - REMOVAL

FSN/FSCA: FA 2016-08

Affected Product:

Avenir® Müller Stem 6 Lateral uncemented- REF: 01.06010.106, LOT: 4023094 Avenir® Müller Stem 4 Standard uncemented- REF: 01.06010.004, LOT: 4022860

Dear Sirs,

Zimmer GmbH is initiating a voluntary removal of two lots Avenir Müller Stems (as indicated above) that may be in your inventories. The Avenir Müller Stem 6 lateral uncemented might be placed in the packaging of the Avenir Müller Stem 4 standard uncemented and vice versa.

Our records indicate that you may have received one or more of the affected products.

Risks

- 1) A slight delay in the surgery time might occur if after the discovery of the issue prior implantation, a new product has been made available to finalize the surgery accordingly.
- 2) If no similar implant is available, the doctor might choose a one size bigger stem and further rasp the bone for preparation which induces a delay in surgery. Potentially the length of the new implant size might create the dissymmetry in patient's leg.
- 3) The surgeon might have to change the surgical approach and chose a different product conducting to a delay during the surgery or even interrupt / postpone the surgery if there is no appropriate available solution.
- 4) The surgeon might use a standard stem instead of a lateral stem. For the standard stem the offset is 6mm smaller and therefore an increased laxity of the hip might result. This could conduct to a risk of luxation, pain or revision surgery.

Your Responsibilities

- 1. Review the notification immediately and ensure affected personnel are aware of the contents without delay.
- 2. Assist your Zimmer Biomet sales representative with the quarantine of any affected device.
- 3. Your Zimmer Biomet sales representative will remove the affected device, if any, from your facility.
- 4. Complete the Certification of Acknowledgement from (Attachment 1) and return to fieldaction.emea@zimmerbiomet.com.



5. If after reviewing this notification you have further questions or concerns please contact your local Zimmer Biomet representative.

Vigilance/ Reporting Information

This voluntary notification will be reported to the local Competent Authorities.

Any adverse reactions experienced with the use of these products, and/or quality problems may also be reported according to MEDDEV 2.12-1 Rev. 8 or any relevant requirements to the local health authority in your country.

Please keep Zimmer GmbH informed of any adverse events associated with this device or any other Zimmer Biomet product. Adverse events may be reported to Zimmer Biomet at winterthur.per@zimmerbiomet.com, or to your local Zimmer Biomet representative.

Kind regards,	
	_



Attachment 1 Certificate of Acknowledgement

FSN/FSCA: FA 2016-08

Affected	Drad	
ATTECTED	Prod	IICT.

Avenir® Müller Stem 6 Lateral uncemented- REF: 01.06010.106, LOT: 4023094

Avenir® Müller Stem 4 Standard uncemented- REF: 01.06010.004, LOT: 4022860

Worms Manor Storm + Staridard	andemonica REF. 01.00010.00	54, LOT. 4022000
Please email or fax the com	pleted form to your local Zi	mmer Biomet contact
Fax / Email	//	
By signing below, I acknowledgurgent Field Safety Notice – Reaccordance with the notice: 1. Return parts in inventory 2. Fill the list below 3. Sign the form	emoval, and that the require	
Product reference	Quantity received	Quantity to return
All parts received were imp	lanted.	
Printed Name:		
Signature:		
Hospital Name:		

Please maintain a copy of your completed form with your internal records.

Hospital Address:_____

Phone Number: