



رقم المحفوظات: ٧١٢٥

رقم الصادر: ١٢/٧/٢٠١٢

بيروت، في:

٢٩ آب ٢٠١٢

جانب نقيب المستشفيات الخاصة في لبنان

الموضوع: إشعار بمتابعة جهاز طبي

Wood Applicator Swab, Fisherbrand Sterile Swab, Calcium Alginate Fiber Tipped

الجهاز المعنى بالمتابعة:

- Wood Applicator Swab, Fisherbrand Sterile Swab, Calcium Alginate Fiber Tipped.
- Trade Mark: Fisher Scientific Co
- Local Representative:

بناء على التقرير الصادر عن وكالة ال FDA

والتوصية الصادرة عن الشركة المصنعة والتي تشير الى وجود خلل في عملية تصنيع الصنف المذكور اعلاه، نرجو منكم تعميم هذه النشرة على جميع المستشفيات المعنية.

مرفق ربطاً:


- التقرير الصادر عن وكالة ال FDA

يبلغ:

- دائرة البرامج والمشاريع
- المستشفيات الحكومية
- المحفوظات

مدير عام الصحة

د. وليد عمّار



[FDA Home](#)³ [Medical Devices](#)⁴ [Databases](#)⁵

Medical & Radiation Emitting Device Recalls




[510\(k\)](#)⁷ | [Registration & Listing](#)⁸ | [Adverse Events](#)⁹ | [Recalls](#)¹⁰ | [PMA](#)¹¹ | [Classification](#)¹² | [Standards](#)¹³ | [Inspections](#)¹⁴ | [CFR Title 21](#)¹⁵ | [Radiation-Emitting Products](#)¹⁶ | [X-Ray Assembler](#)¹⁷ | [Medsun Reports](#)¹⁸ | [CLIA](#)¹⁹ | [TPLC](#)²⁰

[New Search](#)

[Back to Search Results](#)

**Class 2 Recall
Fisherbrand Sterile Swabs**



Date Posted	August 12, 2013
Recall Number	Z-1955-2013
Product	Fisherbrand Sterile Swab, Calcium Alginate Fiber Tipped, Wood Applicator Swab 100 pouches/boxes, 10 boxes/case. Used in applying medications to or take specimens from a patient.
Code Information	Product code # 14-959-81, lot #61513, expiration date: 2014-08, and lot 8710, expiration date 2014-08.
Recalling Firm/Manufacturer	Fisher Scientific Co 300 Industry Dr Pittsburgh, Pennsylvania 15275-1001
Consumer Instructions	Contact the recalling firm for information
For Additional Information Contact	Fisher Scientific Co. Customer Service 724-517-1500
Reason for Recall	The firm is recalling Fisherbrand Sterile Swabs due to 4 customer complaints reporting the presence of non-pathogenic organisms in two lots. The finding was confirmed in lot 61513 and lot 8710 is also being recalled as a precautionary measure.
Action	Customers were notified by letter on June 18, 2013 and requested to discontinue use and return all affected product. The firm also asked that any additional affected customer base be contacted and notified of the recall if the lots had been further distributed. If you have any questions, contact Stericycle (reference "Event 4070") at 1-877-410-5558.
Quantity in Commerce	1230
Distribution	Nationwide and the country of Canada.

Links on this page:

1. <http://www.addthis.com/bookmark.php?u508=true&v=152&username=fdamain>
2. <http://www.addthis.com/bookmark.php>
3. <http://www.fda.gov/default.htm>
4. <http://www.fda.gov/MedicalDevices/default.htm>
5. <http://www.fda.gov/MedicalDevices/DeviceRegulationandGuidance/Databases/default.htm>
6. </scripts/cdrh/devicesatfda/index.cfm>
7. </scripts/cdrh/cfdocs/cfPMN/pmn.cfm>
8. </scripts/cdrh/cfdocs/cfRL/rl.cfm>
9. </scripts/cdrh/cfdocs/cfMAUDE/TextSearch.cfm>
10. </scripts/cdrh/cfdocs/cfRES/res.cfm>
11. </scripts/cdrh/cfdocs/cfPMA/pma.cfm>
12. </scripts/cdrh/cfdocs/cfPCD/classification.cfm>
13. </scripts/cdrh/cfdocs/cfStandards/search.cfm>
14. </scripts/cdrh/cfdocs/cfTPLC/inspect.cfm>
15. </scripts/cdrh/cfdocs/cfCFR/CFRSearch.cfm>
16. /scripts/cdrh/cfdocs/cfPCD_RH/classification.cfm
17. </scripts/cdrh/cfdocs/cfAssem/assembler.cfm>
18. </scripts/cdrh/cfdocs/Medsun/searchReportText.cfm>
19. </scripts/cdrh/cfdocs/cfClia/Search.cfm>
20. </scripts/cdrh/cfdocs/cfTPLC/tplc.cfm>
21. http://www.accessdata.fda.gov/scripts/cdrh/cfdocs/relateditems.cfm?page_title=medical%20device%20recalls&item1_text=medical%20device%20recalls%20&item1_url=www.fda.gov/medicaldevices/safety/recalls/corrections/removals/listofrecalls/default.htm&item2_text=fda%20enforcement%20report%20index&item2_url=www.fda.gov/safety/recalls/enforcementreports/default.htm

Page Last Updated: 08/20/2013