

Dear distributor,

DORC became aware that the use of the 1363.DD VFI Pack for Silicone oil syringes in combination with certain batches of 10ml prefilled glass syringes containing silicone oil (i.e. SIL-1000-S and SIL-5000-S with expiry dates as of 2017-12) could result in breaking of the finger flange of the glass syringe, leaving the contents of the syringe (silicone oil) untouched.

The following products are potentially affected:

Article number	Description	Batch number			
1363.DD	VFI Pack for Silicone Oil syringes		140585	160291	170775
			1406103	160390	170806
			140630	1604113	170939
			140638	160515	171009
		П	140919	160612	1712140
		П	140973	160786	1712150
		П	141051	160821	1712168
			150301	160931	171218
			150473	160937	171260
			1505133	160949	180135
			150518	161148	180209
			150614	161216	1802100
			150778	170120	180370
			150820	170272	1804121
			150992	170311	1804148
			151079	1704186	1804149
			151108	170473	1804180
			151196	170512	1806149
			151227	170599	180628
			151248	170628	180745
			160167	170704	1808166
			160225	1707135	

Root cause analysis revealed that the problem is due to the combined use of the syringe and the adaptor. In extreme tolerance fields of the adaptor and the syringe there is a transgression force build up between the adapter and the syringe, incidentally resulting in breaking of the syringe flange.

Dutch Ophthalmic Research Center

D.O.R.C. International

P.O. Box 43 3214 ZG Zuidland The Netherlands

Visiting address Kerkweg 47e 3214 VC Zuidland

Delivery address Scheijdelveweg 2 3214 VN Zuidland


- T (+31) (0) 181 45 80 80
- (+31) (0) 181 45 80 90
- E mailto@dorc.eu
- W www.dorc.eu

VAT no. NL008190057B01 Chamber of Commerce 24167879

Rabobank Rotterdam Swift RABONI 211 EORI NL008189778 IBAN NL54 RABO 0238 1753 08







Breaking of the flange of the glass prefilled silicone oil syringe (i.e. SIL-1000-S and SIL-5000-S) is related to the following potential harms:

- Wound damage: due to the breakage the surgeon might make a sudden movement which can increase the sclerotomy
- Tissue damage: the glass might cut the user.

Please note that all silicone oil batches supplied to your country can be safely used with the current adaptor (i.e. 1363.DD). However, as a preventive measure, in order to prevent potential breaking of the finger flange of the glass prefilled silicone oil syringes (i.e. SIL-1000-S and SIL-5000-S) with an expiry date as of 2017-12 the distribution of these batches to your country will be on hold as long as the current VFI Pack for Silicone Oil syringes (i.e. 1363.DD) is available at your customers to be used in combination with prefilled glass syringes containing silicone oil (i.e. SIL-1000-S and SIL-5000-S with an expiry date as of 2017-12).

D.O.R.C. has initiated a design change of the syringe adaptor included in the VFI pack (i.e. 1363.DD) to solve this potential issue. When available this adaptor can be supplied to customers as an exchange for the current syringe adaptor.

Please inform me with regard to your activities to notify this issue to the national competent authority in compliance with local legislation and the follow-up to end-users to exchange the current VFI Pack for Silicone Oil syringes (i.e. 1363.DD) for the new design when available. Please ensure that D.O.R.C. receives completed Distributor Reply Forms and Customer Reply forms prior to the return of the current VFI Pack for Silicone Oil syringes (i.e. 1363.DD).

D.O.R.C. Dutch Ophthalmic Research Center (International) B.V. apologizes for any inconvenience caused by this problem.

Manager RA

Date: 07-09-2015

D.O.R.C. Dutch Ophthalmic Research Center (International) B.V. Scheijdelveweg 2 3214 VN Zuidland The Netherlands